













Thaw Hall









Current Arial photo from Google Earth



















- REMOVE, REPAIR STEEL AS REQD, REATTACH
- 2. REMOVE AND REPLACE GRANITE/TC ROSETTE TO MATCH EXISTING
- 3. NO WORK














Questions?









123:-University Club, Pittsburgh, Pa.


















RENDER - RAILING DETAIL INSIDE VIEW












LIGHTING FIXTURE TYPE 'B' DETAIL
















EXISTING GUARD TO BE RAISED AND REBUILT



